	Estimated Bond Timeline		
	2015-2017 Series 2015	2017-2019 Series 2017	2019-2024 Series 2019
Brannen Elementary School Description			
HVAC equipment replacement - RTU replacement, Central Plant equipment, Cooling			
Tower replacement			
Replacement of Facility			
Consider consolidation with Ney or vice versa			
Polk Elementary Description			
Outdated, undersized Kitchen equipment replace all			
MEP equipment replacement - per DBR report			
Electrical power inadequate - upgrade main service			
Drop-off/pick-up vehicular circulation			
Limited parking			
Office access insecure - relocate office			
Lack Gymnasium			
Repurpose library into collaborative media center			
Refigure all to meet Texas Dept of Licensing & Regulations (TDLR)			
Add 4 Classrooms			
Building Exterior Improvements			
Saliding Excertor improvements			
Ney Elementary Description			
MEP equipment replacement major equipment			
Consolidate with other LJ Elementaries (Demo)			
Beutel Elementary Description			
Replacement			
Griffith Elementary			
Description			
Building envelope in poor condition - new windows, tuckpoint, recaulk, facia,etc. 12,000 sf @\$40/sf			
Outdated, undersized Kitchen equipment - replace lump sum			
Lack car stacking space			
Replace boiler			
Lack Gymnasium			
Increase data and power drops (limited data drops needed)			
Repurpose library into collaborative media center			
Accessibility at restrooms. Reconfigure all to meet TDLR			
Building Exterior Improvements			
Addition of 4 classrooms			
Ogg Elementary			
Description			
Replacement			
Dohorto Flomentory			
Roberts Elementary Description			
Replacement			

Austin Elementary School Description MEP equipment replacement - per DBR report	2015-2017 Series 2015	2017-2019	2019-2024
Description MEP equipment replacement - per DBR report	_	Series 2017	Series 2019
Outdated, undersized Kitchen equip - replace lump sum			
Building envelope in poor condition - new windows, tuckpoint, recaulk, facia,etc. 12,000 sf @\$40/sf			
Backup Generator for water supply		·	
Lack Gymnasium			
Repurpose library into collaborative media center			
Accessibility at restrooms. Reconfigure all to meet TDLR		<u></u>	
Update interior finishes			
Eliminate outbuildings			
Replace outbuildings with 8 classrooms			
neplace outbuildings with a classicoms			
Velasco Elementary School			
Description			
Cooling tower corrosion issues - replace			
Repurpose library into collaborative media center			
Inadequate parking			
Covered pick-up area @ McNeil - scope?			
Building Exterior Improvements			
Fleming Elementary School Description			
Consider Consolidation with Long			
501010010011001101111111111111111111111			
Long Elementary Description			
Replacement			
Consider Consolidation with Fleming			
Rasco Middle School Description			
HVAC controls issue			
Site circulation; cars and busses share drive			
Replaced selected roofing			
Increase data and power drops (Limited data drops needed)			
Repurpose library into collaborative media center		-	
Building Exterior Improvements			
Relocation of the Front Office			
Lanier Middle School Description			
Replace Central Plant equipment and MEP systems (Older Wing)			
Open access to outbuildings - add fencing, access control		<u> </u>	
Kepiace Gymnasium			
Replace Gymnasium Repurpose library into collaborative media center		·	!

	Estimated Bond Timeline		
	2015-2017 Series 2015	2017-2019 Series 2017	2019-2024 Series 2019
Lake Jackson Intermediate School Description			
Open access to outbuildings - add fencing, access control			
Covered Walkway to outbuilding			
Renovate Gymnasium - floor, bleachers,			
Repurpose library into collaborative media center			
Replace press box @ football field - allowance			
Building Exterior Improvements			
Clute Intermediate School Description			
Replace flooring @ east gymnasium			
Replace "Cottage" program currently in church; 20 students			
Demolish former church			
Repurpose library into collaborative media center			
Replace press box @ football field - allowance			
Building Exterior Improvements			
Freeport Intermediate School			
Description			
Replace HVAC equipment - Cooling tower, fans, RTUs			
Replace roof			
Gym flooring replacement			
Upgrade athletic facilites; locker rooms, track			
Repurpose library into collaborative media center			
Building Exterior Improvements			
Brazoswood High School Description			
·			
MEP equipment replacement; pumps, piping, etc. Replace roof			
HVAC concerns throughout - comprehensive repair and replace program			
Increase size of student parking lot (students currently parking Slade Field) - add 200			
spots @ \$1500 each			
Improve Parking Lot at Slade Field			
Repurpose library into collaborative media center			
Update interior finishes			
Committee add - "Face Lift" to improve community presence			
Auditorium upgrades and improvements			
Swimming Pool Upgrades (Locker rooms, showers, office area, seating)	+		
CTE Program Improvements	+		
Turf replacement at Slade Field			
Brazosport High School			
Description			
Waterproofing at Auditorium			
Black Box lighting and sound sytem - allowance			
Repurpose library into collaborative media center			
CTE Program Improvements			
Building Exterior Improvements			

	Estimated Bond Timeline		
	2015-2017 Series 2015	2017-2019 Series 2017	2019-2024 Series 2019
Lighthouse Learning			
Description			
Upgrade food service equipment - allowance			
Inconsistent HVAC operation - comprehensive repair and selected replacement			
Building Exterior Improvements			
Administration Building Description			
Replace mechanical units			
Galvanized piping replacement - main line only			
Access - restrooms, entries, ramps - allowance			
Update interior finishes			
Update lighting			
Child Nutrition / Transportation / Maintenance Description			
Upgrade office area and restroom finishes			
Doors/Entrances in poor condition			
Refurbish old cooler to make into office space			
Interior Upgrades and Furnishings			
District Stadium			
Description Replace stadium turf (end of useful life)			
Add public restroom facilities			
Accessibility - concessions, ticket booth - allowance			
Committee add - Replace Track			
Professional Resource Center Description			
Building exterior improvements - Allowance landscaping, signage, hardscape, painting, masonry			
Roof Replacement			